Oil Field Environmental Incident Summary

Date/Time of Notice: 03/14/2016 12:35 Incident: 20160314123518 Responsible Party: DENBURY ONSHORE, LLC Well Operator: DENBURY ONSHORE, LLC Well Name: MOSSER 2-22 Field Name: T. R. Well File #: 6659 Date Incident: 3/13/2016 Time Incident: 08:40 Facility ID Number: **BILLINGS** Twp: 141 Rna: 101 Sec: 22 Qtr: County: Location Description: On location Submitted By: David Hill Received By: **Brian Ehrmantraut** Contact Person: 5320 LEGACY DR PLANO. TX 75024-3127 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 1 Mile Distance Nearest Occupied Building: 0.1 Mile Distance Nearest Water Well: Type of Incident: Vessel Leak Release Contained in Dike: Yes - Within Dike Reported to NRC: No Units Spilled Recovered Units Followup **Units** Oil **Brine Barrels Barrels** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None

Areal Extent:

Contained within dike.

Potential Environmental Impacts:

None

Action Taken or Planned:

The well was shut in and the treater was drained into the facility tanks. A vac truck was dispatched to suck up the standing fluid. The contaminated soil will be excavated and hauled to an approved landfill. The treater will be repaired and recoated.

Wastes Disposal Location: Recovered liquids were pumped into facility tanks on location.

Recovered solids will be disposed at an approved landfill.

Agencies Involved: BLM

Updates

Date: 3/14/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a vessel leak, remained within the diking according to the report. NDIC retains oversight.